ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M127011
Date Received: 01/06/11
Date Extracted: 01/07/11
Date Analyzed: 01/07/11
Matrix: Water
Units: ug/L (ppb)

Client: Project: Lab ID: Alaskan Copper Works Metro Self Monitor M127011

Lab ID: 101040-01 x10
Data File: 101040-01 x10.026

Instrument: ICPMS1 Operator: AP

Lower

Upper Limit:

Internal Standard: Germanium

Analyte:

% Recovery: 85

Limit: 60

Limit 125

Concentration ug/L (ppb)

 Chromium
 439

 Nickel
 456

 Copper
 287

 Zinc
 14.8

ENVIRONMENTAL CHEMISTS

Client:

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank
Date Received: Not Applicable
Date Extracted: 01/07/11
Date Analyzed: 01/07/11
Matrix: Water
Units: ug/L (ppb)

Project: Metro Self Monitor M127011
Lab ID: I1-14 mb
Data File: I1-14 mb.018
Instrument: ICPMS1
Operator: AP

Alaskan Copper Works

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 87 60 125

Concentration ug/L (ppb)

Chromium <1
Nickel <1
Copper <1
Zinc <1

ENVIRONMENTAL CHEMISTS

Date of Report: 01/11/11 Date Received: 01/06/11

Project: Metro Self Monitor M127011, F&BI 101040

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 101031-01 (Matrix Spike)

Analyte	Reporting Units	Spike Level	Sample Result	Percent Recovery MS	Percent Recovery MSD	Acceptance Criteria	RPD (Limit 20)
Chromium	ug/L (ppb)	20	1.83	105	106	67-132	1
Nickel	ug/L (ppb)	20	12.3	103 b	96 b	73-119	7 b
Copper	ug/L (ppb)	20	20.9	99 b	93 b	50-144	6 b
Zinc	ug/L (ppb)	50	21.0	99 b	98 b	46-148	1 b

Laboratory Code: Laboratory Control Sample

	Percent										
	Reporting	Spike	Recovery	Acceptance							
Analyte	Units	Level	LCS	Criteria							
Chromium	ug/L (ppb)	20	100	66-135							
Nickel	ug/L (ppb)	20	106	67-134							
Copper	ug/L (ppb)	20	105	66-134							
Zinc	ug/L (ppb)	50	101	57-135							

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- x The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

101040 s	AMPLE CHAIN OF CUSTODY	ME 011	66/2011 AI4	
Send Report To Genzio THOMPSON Company AUSKAN COMPER WORKS Address 628 5. HAWFORD 57	PROJECT NAME/NO. METRO SECT Monitor	Page # of		
City, State, ZIP SAME WA 98134 Phone # 206-571-6033 Fax # 206-382-4307	REMARKS	SAMPLE DISPOSAL Dispose after 30 days Return samples Will call with instructions		

							ANALYSES REQUESTED											
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	VOCs by 8260	SVOCs by 8270	IIFS	OR CLA ME ZN						Notes
m 127011	01	1/6/11	12:30	Azo	1					Tue D	77.11	X	7. T			977 1276	print retu	
			_117,7															
					No.ex.		5 [-		-	200					7/2		1,7 5
								11	-					17.	143.			
is and the second																16-		
		1							-	S	ımj	les	ecei	ved	aţ_	18		parie - se
14				-		П		7	-		11				77.		Carrier Control	
Friedman & Bruya, Inc. 3012 16th Avenue West	SIGNATURE Relinquistry:			PRINT NAME					COMPANY ACW FeBI					1//	DATE	TIME 1.24 pm		
Seattle, WA 98119-2029 Ph. (206) 285-8282	Received by: Relinquished by	Jan	an f	h	an					Fe.	B_T			_	6/11	V		
T. T	Received by:	1 N		751	-7.7	SILE	rea le	3125	150	+				27				100
ORMS\COC\COC.DOC	Carl Called		ET THAPTE	the state of the		7-197	alve Ave	1271		ha E	771 T	71 8	0.0104				100	102131

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

January 11, 2011

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on January 6, 2011 from the Metro Self Monitor M127011, F&BI 101040 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0111R.DOC